JOINS



This operation is called splicing.

The aim is to make loops or to integrate spirals, with the warp yarn at either end of the product in order to make it circular.

Step 1: unweaving the canvas at both ends (A and B) for a length of 20cm then moving the weft threads down with a needle by 2.5cm.

Step 2: preparing the band and unweaving it for 60-70 cm.

Step 3: installing the band onto the machine.

